

I hereby certify that this paper (along with any paper referred to as being attached or enclosed) is being deposited with the U.S. Postal Service on the date shown below with sufficient postage as First Class Mail, in an envelope addressed to: Attention: Certificate of Correction Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450. JUL 16 2007

Docket No.: 06005/37172 (PATENT)

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Letters Patent of: Robert B. Havekost

Patent No.: 7.113.085

Issued: September 26, 2006

For: ENHANCED DEVICE ALARMS IN A PROCESS CONTROL SYSTEM

REQUEST FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 CFR 1.323 Certificate JUL 1 8 2007 of Correction

Attention: Certificate of Correction Branch

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

Dear Sir:

Upon reviewing the above-identified patent, Patentee noted typographical errors which should be corrected

In the Specification:

At page 10, line 27, Applicant error, "indicting" should be -- indicating --.

At page 14, line 8, PTO error, "alarm functions" should be -- alarm functions

At page 17, line 9, Applicant error, "to great or to small" should be -- too great or too small ---

07/17/2207 MGEPRENI 80020015 7113085

At page 17, line 10, Applicant error, "to high or follow" should be -- too highs. 92 OP A 100 . or too low --.

JUL 18 2007

Patent No.: 7,113,085 Docket No.: 06005/37172

At page 25, line 21, Applicant error, "arms" should be -- alarms --.

At page 26, line 10, Applicant error, "condition led" should be -- condition that led --.

At page 28, line 16, Applicant error, "a-configurable" should be -- non-configurable --.

At page 28, line 17, Applicant error, "COMM, FAILED," should be -- "COMM," "FAILED," --.

At page 30, line 10, Applicant error, "applications can" should be -- applications and can --.

At page 37, line 30, Applicant error, "alarms" should be -- alarm --.

The errors were found in the application as filed by applicant. Our check in the amount of \$100.00 covering the fee set forth in 37 CFR 1.20(a) is enclosed.

The errors now sought to be corrected are inadvertent typographical errors the correction of which does not involve new matter or require reexamination.

Transmitted herewith is a proposed Certificate of Correction effecting such amendment. Patentee respectfully solicits the granting of the requested Certificate of Correction.

Patent No.: 7,113,085 Docket No.: 06005/37172

The Director is hereby authorized to charge any deficiency in the fees filed, asserted to be filed or which should have been filed herewith (or with any paper hereafter filed in this application by this firm) to our Deposit Account No. 13-2855, under Order No. 06005/37172.

Dated: July 11, 2007

Respectfully submitted,

By ZnAltec Roger A. Heppermann

Registration No.: 37,641

MARSHALL, GERSTEIN & BORUN LLP

233 S. Wacker Drive, Suite 6300

Sears Tower

Chicago, Illinois 60606-6357

(312) 474-6300

Attorney for Applicant

PTO/SB/44 (05-07)

Approved for use through INSI/12007. OM8 0955-0033

U.S. Patent and Trademark Office, U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

By Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

By Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO.

7.113.085

APPLICATION NO.

09/838,494

ISSUE DATE

September 26, 2006

INVENTOR(S) : Robert B. Havekost

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Specification:

At Column 7, lines 20-21, "indicting" should be -- indicating --.

At Column 9, line 26, "alarm f unctions" should be -- alarm functions --.

At Column 11, lines 19-20, "to great or to small" should be -- too great or too small --.

At Column 11, line 21, "to high or to low" should be -- too high or too low --.

At Column 16, line 40, "arms" should be -- alarms --.

At Column 17, line 1, "condition led" should be -- condition that led --.

At Column 18, line 25, "a-configurable" should be -- non-configurable --

At Column 18, line 26, "COMM, FAILED," should be -- "COMM," "FAILED." --.

At Column 19, line 32, "application can" should be -- applications and can --.

At Column 24, line 24, "alarms" should be -- alarm --.

MAILING ADDRESS OF SENDER (Please do not use customer number below):
Roger A. Heppermann
MARSHALL, GERSTEIN & BORUN LLP 1
233 S. Wacker Drive, Suite 6300
Sears Tower

Chicago, Illinois 60606-6357

